

Safety Issue Type: Recalls

September 20 2019 NHTSA Campaign Number: 19V675000

Oil Leak From Airbox Hose

The leaking oil may drip in the path of the rear tire, increasing the risk of a crash.

NHTSA Campaign Number 19V675000

Manufacturer Ducati North America

Components ENGINE

Potential Number of Units Affected 651

Summary

Ducati North America (Ducati) is recalling certain 2014-2018 1199 SL, Panigale R (V2), 1299 SL, and 1299 FE motorcycles. Engine crankcase pressure can push engine oil into the airbox, possibly resulting in oil leaking from the airbox drain hose.

Remedy

Ducati will notify owners, and dealers will install a blow-by valve kit, free of charge. The recall is expected to begin October 28, 2019. Owners may contact Ducati customer service at 1-888-391-5446. Ducati's number for this recall is SRV-RCL-19-002.

Notes

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

Affected Products (15)

Vehicle

MAKE	MODEL	YEAR
DUCATI	1199	2014-2018
DUCATI	1299	2014-2018
DUCATI	PANIGALE R	2014-2018

Associated Documents (4)

Safety Bulletin

RCSB-19V675-9931.pdf 2900.422KB

<https://static.nhtsa.gov/odi/rcl/2019/RCSB-19V675-9931.pdf>

Recall Acknowledgement

RCAK-19V675-1175.pdf 245.094KB

<https://static.nhtsa.gov/odi/rcl/2019/RCAK-19V675-1175.pdf>

Safety Bulletin

RCSB-19V675-3265.pdf 2076.257KB

<https://static.nhtsa.gov/odi/rcl/2019/RCSB-19V675-3265.pdf>

Defect Notice 573 Report

RCLRPT-19V675-1546.PDF 213.769KB

<https://static.nhtsa.gov/odi/rcl/2019/RCLRPT-19V675-1546.PDF>